

| | DBs | Time Stamp | C o m m e n t s | E r r o r D e f i n i t i o | Errors |
|----|---|---------------------|--------------------------------------|--|--------|
| 1 | USPAT | 2003/05/22 10:14 | | | 0 |
| 2 | USPAT | 2003/05/22 10:14 | | | 0 |
| 3 | USPAT | 2003/05/22 10:15 | | | 0 |
| 4 | USPAT | 2003/05/22 10:16 | | | 0 |
| 5 | USPAT | 2003/05/22 10:04 | | | 0 |
| 6 | US-PGPUB ; EPO; JPO; DERWENT; IBM_TDB | 2003/05/22 10:04 | | | 0 |
| 7 | US-PGPUB ; EPO; JPO; DERWENT; IBM_TDB | 2003/05/22 10:14 | | | 0 |
| 8 | US-PGPUB ; EPO; JPO; DERWENT; IBM_TDB | 2003/05/22 10:15 | | | 0 |
| 9 | US-PGPUB ; EPO; JPO; DERWENT; IBM_TDB | 2003/05/22 10:15 | | | 0 |
| 10 | US-PGPUB ; EPO; JPO; DERWENT; IBM_TDB | 2003/05/22 10:16 | | | 0 |

| | Type | L # | Hits | Search Text |
|----|------|-----|------|--|
| 1 | BRS | L1 | 2489 | laser with stress\$3 |
| 2 | BRS | L2 | 271 | 1 with (reduct\$4 or relief or reliev\$3 or eliminat\$3) |
| 3 | BRS | L3 | 0 | 2 and dmd |
| 4 | BRS | L4 | 1 | 2 and (direct adj (material or metal) adj deposit\$4) |
| 5 | BRS | L5 | 71 | laser with (stress\$3 near7 control\$4) |
| 6 | BRS | L6 | 70 | laser with (stress\$3 near7 control\$4) |
| 7 | BRS | L7 | 2003 | laser with stress\$3 |
| 8 | BRS | L9 | 0 | 8 and dmd |
| 9 | BRS | L10 | 0 | 8 and (direct adj (material or metal) adj deposit\$4) |
| 10 | BRS | L8 | 157 | 7 with (reduct\$4 or relief or reliev\$3 or eliminat\$3) |